




DESCRIPTION

This document illustrates how to select the proper blower motor assembly for Model 925 warmers.

NOTES


Motors are not retrofittable.

0016406




**BLOWER MOTOR
ASSEMBLY**

0018644



**BLOWER MOTOR
ASSEMBLY**

0022309



BLOWER MOTOR