




DESCRIPTION

This document illustrates how to select the proper blower motor assembly for Model 695 Series warmers.

NOTES

Motors are not retrofittable.


Model 695 / 695B




0017207SK

Model 695C


Compare with your unit for the proper replacement blower motor assembly.



0021023



0021012




0018632

0022309

0018631

0017230 (x8)

Model 695D



0022309